

Belzona Long Term Step Repairs



Broken & Worn with the failing nose treads removed.



Belzona 4111 (light color) repairs the worn and broken steps awaiting the non slip system



The steps 5 years later, still in excellent condition.

STATISTICS

CUSTOMER
Hospital

APPLICATION DATE
2003

SUBSTRATE
Concrete

PRODUCTS
Belzona 4111
Belzona 5811
Belzona 9211

APPLICATION SITUATION

Hospital in Charleston, SC had serious concerns about worn and damaged stairs to a busy entrance.

PROBLEM

The damaged stairs posed a potential for serious injuries and expensive liabilities.

APPLICATION METHOD

The application was carried in accordance to FPA-1 and FPA-8.

BELZONA FACTS

Belzona step repairs are long term and extremely cost effective. Minimal down time and long term service. The steps were checked in 2010 (7 years later and are still in excellent condition).